

Variable Valves - Plus More

We'll finish up some old business in this *CounterPoint*, before embarking on a closely related topic.



This issue's case study was contributed by John Thornton.

Last time (Fall 2010), we looked at two Nissan variable valve timing case studies, provided by John Thornton. There wasn't enough room in that issue for John's very informative third case study, so it's included here. After we've finished with the third case study, we'll move into an overview of the construction, operation and diagnosis of various crank sensor designs. Let's get started.

Our third case study involves a 2001 Nissan Sentra GXE, also with the 1.8L QG18DE engine found in the first two case studies. The vehicle failed an Illinois OBD II inspection for a P0335 crank sensor diagnostic trouble code (DTC). If the DTC is cleared, it resets very quickly and matures to a stored DTC. The code definition suggests that a DTC P0335 may be caused by a POS/PHASE sensor synch issue. The engine also surged at idle. Figure 1 on page 3 illustrates the idle surge in PARK and DRIVE.

The QG18DE engine is equipped with variable intake cam valve timing. By default, the intake cam timing reverts to its fully retarded position. All measurements are in crankshaft degrees.

You're no doubt familiar with the acronym for top dead center (TDC). If an event occurs before or after top dead center the acronyms BTDC and ATDC are used. Valve events may also occur before or after bottom dead center and the acronyms BBDC and ABDC are used for those.

Without intake cam timing advance (fully retarded):

- the intake valve opens at 3° ATDC
- the intake valve closes at 57° ABDC
- the exhaust valve opens at 38° BBDC
- the exhaust valve closes at 4° ATDC
- valve overlap = 1°

When energized, the intake cam is advanced 20 crank degrees. With intake cam timing advance:

- the intake valve now opens at 17° BTDC
- the intake valve now closes at 37° ABDC
- the exhaust valve now opens at 38° BBDC
- the exhaust valve now closes at 4° ATDC
- valve overlap = 21°

In the 2003 model year, Nissan eliminated the exhaust camshaft sensor on its 1.8L engines. The intake camshaft sensor is used for synch as well as to control intake cam

phasing. The intake camshaft sensor is driven off the back of the intake camshaft. The crankshaft reluctor was also changed. It has two missing teeth, followed by 16 teeth, then two missing teeth followed by 16 more teeth. This means there would have been 36 teeth if all were present.

Refer to the waveforms in Figures 2 and 3 on page 3. The crank (POS) and exhaust cam (PHASE) sensor waveforms are in their usual locations, but we've added a third waveform at the top. This waveform was produced by the intake camshaft sensor.

When energized, the variable valve timing system should advance the intake cam timing by 20 crankshaft degrees. However, the exhaust cam sensor waveform appears to be retarded by about 10 crank degrees. The timing chain is probably stretched, which also caused the P0355. Although the variable valve timing mechanism causes the intake camshaft to advance as it should, the intake camshaft timing also is about 20 crankshaft degrees retarded. This is probably responsible for the surge. The intake cam sprocket may have jumped a tooth, or there may be another mechanical explanation.

Using an oscilloscope attached to the crank and cam sensors allows us to diagnose engine mechanical faults without engine disassembly. Knowing what you'll find before you remove a single bolt saves you from a potential misdiagnosis and a lot of wasted time and it also allows you to provide the customer with a more accurate estimate of repair costs.

Crankshaft Position Sensors

The crankshaft position sensor (CKP) helps the PCM determine when each piston reaches top dead center (TDC). To time the ignition event for each cylinder, the PCM calculates the position of the crankshaft's connecting rod journal in relation to TDC. For example, the PCM might time the spark event to occur

continued on page 3

Fine Tuning



Fine Tuning questions are answered by Mark Hicks, Technical Services Manager. Please send your questions to: **Mark Hicks c/o Wells Vehicle Electronics, P.O. Box 70, Fond du Lac, WI 54936-0070** or e-mail him at technical@wellsmfgcorp.com. We'll send you a very nice Wells golf shirt if your question is published. So please include your shirt size with your question.

Q: We are working on a 2005 Kia Rio with a 1.6L DOHC engine and 65,000 miles on it. The customer complained of a loss of power. We road tested it and he was right — the engine had no power at all. The engine seemed to idle fine but when we stepped on the accelerator there was very little response from the engine.


It first appeared that the converters were restricted. The backpressure was good, but to be sure we moved the manifold away from the head and there was no change in performance. We also checked the timing belt position, as well as fuel pressure, pulse width, MAF, CTS and IAT. We checked for any unmetered air or intake air restriction and everything was to specs. We scoped the cam and crank sensors and they never missed a beat.

I have had three techs working on this for an entire day! Where can we go from here?

**Robert Reuss
Bob's Garage
Menomonee Falls, WI**

A: While consulting with Bob, we suggested looking at the CKP and CMP patterns. After collecting the data, he found he did not have known-good patterns to compare them to. While looking at the patterns a second time, it appeared to Bob and one of his top techs that the CKP had changed or moved. His tech then turned the engine with a pry bar. While applying leverage on the exciter ring gear, it seemed like it slipped. This justified removing the transmission to take a closer look.


The painted arrows in this photo highlight assembly marks on the flywheel and exciter ring gear. These marks should be aligned.



As you can see clearly in the photo above, the exciter ring gear had moved. The ring gear is an interference shrink fit to the flywheel, with

what appear to be punch marks for insurance. There are no actual spot welds to hold it in place. After replacing the flywheel (the dealer had two in stock), the engine ran great again.

The question is what could have made the exciter ring slip? After looking a little closer, it appeared there was some heat discoloration where the clutch disc contacted the flywheel. I talked with Bob and he said the clutch had been replaced twice in this vehicle. Keep in mind that it has only 65,000 miles on it. Does this indicate a problem with the pressure plate, clutch disc or the driver's habit of riding the clutch? It is unknown at this time, but it does appear excessive heat had something to do with the exciter ring movement.



The screen capture above shows known-good crank and cam sensor patterns taken from a 2004 Kia Rio with a standard transmission. These patterns are also available on our website.

Last issue's diagnostic problem from Wayne Brown concerned a 1997 Ford Taurus LX with a 3.0L engine. The power steering works okay until the transmission is shifted into Reverse or Drive. Then it becomes very difficult to turn the steering wheel. Occasionally the radio and power windows will also stop working.

When the vehicle is equipped with Variable Assist Power Steering (VAPS), steering assistance increases as RPM drops. When placing the shifter into gear, the Transmission Range (TR) sensor should send a clear signal to the Generic Electronic Module (GEM), alerting the computer system of the action. In this case the TR sensor is internally shorted and as a result most components connected to the GEM function incorrectly. Disconnecting the TR sensor, then retesting the power steering, will confirm a defective TR sensor. Ford technical service bulletin 96-25-5 addresses this issue.

The first *CounterPoint* readers to supply the correct answer to this diagnostic problem were:

Steve Svendsen
Mechanicville, NY

Victor Hernandez
Tuffy's Auto Repair
Apopka, FL

Diagnose The Problem Win A Shirt

We have had a 2000 Chevrolet Malibu 3.1 in the shop for a couple of days now. The problem is that the turn signals and emergency flashers do not work.

We have checked the fuses, bulbs, sockets and wiring of the system and everything looks good. The brake and tail lights are working. In a moment of desperation I replaced the turn signal switch, but the problem remained. I did notice that when we slightly pressed the emergency flasher switch, the turn signals would momentarily flash. What could be causing this to occur?

Don Lavey
Blue Knob, PA

If you have the answer, contact us at:
E-mail: technical@wellsmfgcorp.com
Fax: (920) 922-3585
Postal: *CounterPoint* Editor
c/o Wells Vehicle Electronics
P.O. Box 70
Fond du Lac, WI 54936-0070

My Hot Links

Follow Wells Vehicle Electronics on:



From time to time, we'll use this space to provide our readers with the addresses of helpful websites we've encountered during our travels on the internet. We hope you find these links to be of value.

Car and Truck Talk USA

www.carandtrucktalk.com

www.ericthecarguy.com

Tune in for a podcast on Sundays at Noon EST with Rich Baxter and Eric The Car Guy.

Technicians Service Training

www.tstseminars.org

Technicians Service Training (TST) is a not-for-profit organization, established to provide quality training seminars and educational materials at a reasonable cost.


This site offers many free webcasts, led by Jerry "G" Truglia, or guest instructors. **WELLS**

Crankshaft Position Sensors

at 10° before top dead center (BTDC) on the compression stroke.


On 1996 and later OBD II-compliant vehicles, the CKP also detects cylinder misfires by measuring very small variations in crankshaft speed. For example, the crankshaft normally decelerates just as a cylinder approaches TDC on compression stroke.

Figure 1: This screen capture illustrates the Nissan Sentra idle surge.




After combustion, the crankshaft accelerates on the power stroke until about 90° after top dead center (ATDC), when cylinder pressure is expended and the angularity of the connecting rod diminishes. When this very predictable deceleration and acceleration pattern is disrupted on a continuing basis, the PCM stores a misfire trouble code for that cylinder.

Figure 2: This is a known-bad pattern. The exhaust cam appears to be retarded about 10 crank degrees.



Most crankshaft position sensors produce a signal using either *variable reluctance (magnetic)* or *Hall effect sensor*. Hall effect sensors produce a digital square wave signal, while magnetic or variable reluctance sensors produce a sine wave pattern. In addition to these basic differences, the amplitude (voltage level) of the output signal of these two sensor types is also different. The Hall effect sensor output voltage level remains consistent throughout the sensor's operating range. The signal is either off (low) or on (high). In contrast, a variable reluctance sensor's output will increase in

Figure 3: The signal from the intake camshaft speed sensor should occur at the dotted line.



amplitude as engine speed increases. The frequency of the signal produced by both sensors give the PCM a direct indication of crankshaft speed and position.

The magnetic reluctance crankshaft position sensor (Figure 4) consists of a single wire wrapped around a permanent magnet, with each end of the wire representing a positive or negative pole. As a rotating ferrous reluctor tooth passes the sensor, it generates an alternating current (AC) signal to the PCM. The signal varies between positive and negative voltage. The PCM reads the sensor signal as it crosses the zero volt line. The accuracy of the reluctance sensor varies slightly due to the voltage switching from positive to negative at slightly different points along the "zero" line.

Figure 4: This crankshaft position sensor is located above a reluctor with a distinctive tooth sequence.



The reluctor for the number one cylinder is slightly modified to provide a signature waveform, indicating to the PCM when that cylinder reaches TDC. When diagnosing a magnetic reluctance sensor, it's important to remember that crank sensor voltage output or amplitude is affected by the air gap between the sensor tip and reluctor, as well as the speed of the reluctor. The accuracy of the reluctance sensor can also be affected if the sensor magnet has attracted particles of ferrous material from clutch linings or other wearing parts.

Hall effect sensors are three-wire sensors that produce a square-wave digital signal that is sent to the PCM. The Hall effect sensor acts as an electrical switch that requires an outside power source and a ground (two of the three sensor wires) to produce the square-wave, on/off

output signal (the third sensor wire). Unlike magnetic reluctance sensors, Hall effect crank position sensors don't rely on higher shaft speeds to generate a useable signal. But like the magnetic reluctance sensor signal, when the crankshaft speed increases, the Hall effect signal frequency also increases.

A somewhat less familiar crankshaft speed sensor is called a *magnetoresistive sensor*. Similar to magnetic reluctance sensors, magnetoresistive sensors use a permanent magnet, tone wheel and two-wire sensor connection. That is where the similarities end.

First, the magnetoresistive sensor is based on the principle of a magnetic field changing the resistance and the current flow through the sensor itself. The magnetoresistive effect is the change of the resistivity of a current-carrying ferromagnetic material due to a magnetic field. And unlike magnetic reluctance sensors, a magnetoresistive sensor can't generate a signal voltage on its own, and requires an external power supply from the PCM.

Inside the sensor is a small integrated circuit containing a magnetoresistive bridge. The magnetoresistive bridge changes resistance due to the relationship between the tone wheel and magnetic field surrounding the sensor. The sensor may contain two magnetoresistive sensors phased slightly apart from each other. Due to this difference in phasing, a magnetoresistive sensor can measure shaft speed and produce a signal at very low rpm.

The sensor's electronic circuitry modifies and amplifies the varying resistance into a direct current (DC) voltage output signal. As the tone wheel rotates and shifts the magnetic field, the sensor changes the voltage and current levels on the signal circuit to the PCM. The magnetoresistive sensor produces a square-wave signal like a Hall Effect sensor. However, the square-wave signal generally will not pull down to zero volts. Instead, the signal will pull from high to low voltage as the circuit resistance changes.

- Other magnetoresistive sensor advantages are:
- Non-contact operation, so there is no wear or friction
 - Due to its high sensitivity, it can be used to measure weak magnetic fields
 - Wide operating frequency range (0 Hz to 1 MHz)
 - Low sensitivity to mechanical stress and less sensitive to vibration than inductive sensors
 - Can be used in harsh environments and at high operating temperatures

We'll be back next time with some quick CKP test procedures, using a scan tool and other diagnostic equipment. **WELLS**

WELLS

WELLS VEHICLE ELECTRONICS
P.O. Box 70
Fond du Lac, WI 54936-0070

Return Service Requested



PRSR STD
U.S. Postage
PAID
Fond du Lac, WI
Permit No. 433

**Variable Valve Timing
Plus More**



**FOR BACK ISSUES VISIT US AT:
www.wellsVE.com**

Hot off the Wire

Technical Video Library Sets YouTube Mark

The Wells Vehicle Electronics brand's extensive library of free online automotive diagnostic training videos has reached two significant milestones on the global YouTube social network, with more than 750,000 views and over 1,100 subscribers.

Developed by the Wells Technical Services department, the video series includes dozens of in-depth training segments covering a broad range of driveability and related topics. The videos can be accessed by searching for "Wells Vehicle Electronics" on YouTube.com and through the company's award-winning



www.wellsVE.com website. Content is available in both English and Spanish.

More than 500,000 of the customer views on YouTube have taken place in just the past year, reflecting the rapidly increasing popularity of the Wells brand among automotive professionals and

consumers. YouTube defines subscribers – the users most coveted by online technical video providers – as regular viewers who have established their own video channels and want to be notified of any additions to a company's library. **WELLS**

Publisher's Information

Wells PresidentDavid Peace
V.P. Sales & MarketingBill Nonnamaker
Technical Services Manager Mark Hicks
Newsletter EditorKarl Seyfert

CounterPoint is a quarterly publication of Wells Vehicle Electronics, P.O. Box 70, Fond du Lac, WI 54936-0070. Letters and comments should be directed to: **CounterPoint** Editor, c/o Wells Vehicle Electronics, P.O. Box 70, Fond du Lac, WI 54936-0070.

© COPYRIGHT 2011 WELLS VEHICLE ELECTRONICS
All rights reserved. No reproduction in whole or part is permitted without the written consent of Wells Vehicle Electronics

SUBSCRIPTION FORM: To receive a quarterly issue of CounterPoint, or to renew your existing subscription, please fill out the form below and mail or fax it to:

CounterPoint
c/o Wells Vehicle Electronics
P.O. Box 70, Fond du Lac, WI 54936-0070
FAX: (920) 922-3585
technical@wellsmfcorp.com

You can also sign up for a CounterPoint digital subscription (PDF) by visiting our website at www.wellsVE.com.

English Spanish Both (Check One)

NAME/TITLE

COMPANY

STREET ADDRESS

CITY, STATE, ZIP CODE

PHONE NUMBER